

Truck 005

**TRUCK OR TRUCK TRACTOR
PREVENTIVE MAINTENANCE REPORT**

Truck & Trailer Repair Center, Inc.
1201 68TH STREET
ROSEDALE, MD 21237
800.715.2982

(MD TR 23-301 — 23-305; COMAR 22.88; FMCSSR 396.17)

Owner's Name Roy Salmon Trucking LLC Address 9737 Eustice Road
Telephone 443-629-4648 ~~Box~~ Randallstown, MD 21133
Make Volvo Model _____ Year 2012
Company Name Roy Salmon Trucking LLC Tag Number 844 F18
Manufacturer's Vehicle ID Number (VIN) 4V4NC9TG6DNS62430
Title Number 47324637

COMAR 11.22.02

	Passed	Failed	Date Repaired*
.02 Alignment	✓		
.03 Suspension	✓		
.04 Steering	✓		
.05 Brake Systems — Hydraulic / Vacuum	N/A		
.06 Brake Systems — Air	✓		
.07 Tires	✓		
.08 Wheels, Rims, Lock Rings, Studs and Nuts	✓		
.09 Accelerator Pedal and Air Throttle	✓		
.10 Fuel Storage and Delivery System	✓		
.11 Exhaust System	✓		
.12 Universal Joints and U-Clamps	✓		
.13 Vehicle Frame, Body and Sheet Metal	✓		
.14 Lighting	✓		
.15 Electrical System	✓		
.16 Emergency Equipment	✓		
.17 Seats and Seat Belts	✓		
.18 Sun Visor	✓		
.19 Mirrors	✓		
.20 Glazing	✓		
.21 Windshield Wipers and Washers	✓		
.22 Defroster	✓		
.23 Auto Trans Gear Selector / Neutral Safety Switch	N/A		
.24 Speedometer and Odometer	✓		
.25 Brake and Clutch Pedal	✓		
.26 Horn	✓		
.27 Hitches and Coupling Devices	✓		
.28 Tanks and Pressure Vessels	✓		

Inspected: (a) Date 01/13/2020

(b) Vehicle Mileage 598803

Inspected by (Print) Kamal Singh

Repaired by (Print) _____

Certified by (Print) [Signature]

Signature [Signature]

(Owner or Authorized Representative)

* Provide description of repairs and parts used on reverse side of this form.