

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER 58037494	FLEET UNIT NUMBER 8683
DATE 04/2021	

MOTOR CARRIER OPERATOR NATIONAL EXPRESS TRANSPORT INC.	INSPECTOR'S NAME (PRINT OR TYPE) Emil KOLEV, KBK Truck and Trailer Repair
ADDRESS 935 N HARVARD AVE.	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE VILLA PARK, IL 60181	VEHICLE IDENTIFICATION (✓) AND COMPLETE <input type="checkbox"/> LIC. PLATE NO. <input checked="" type="checkbox"/> VIN <input type="checkbox"/> OTHER 1GR1P0620LT148683
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED											
OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
OK			1. BRAKE SYSTEM	N/A			4. FUEL SYSTEM	OK			9. FRAME
OK			a. Service Brakes	N/A			a. Visible leak	OK			a. Frame Members
OK			b. Parking Brake System	N/A			b. Fuel tank filler cap missing	OK			b. Tire and Wheel Clearance
OK			c. Brake Drums or Rotors	N/A			c. Fuel tank securely attached	OK			c. Adjustable Axle Assemblies (Sliding Subframes)
OK			d. Brake Hose								
OK			e. Brake Tubing	OK			5. LIGHTING DEVICES				10. TIRES
N/A			f. Low Pressure Warning Device				All lighting devices and reflectors required by Section 393 shall be operable.	N/A			a. Tires on any steering axle of a power unit.
N/A			g. Tractor Protection Valve								b. All other tires.
N/A			h. Air Compressor	OK			6. SAFE LOADING	OK			11. WHEELS AND RIMS
NA			i. Electric Brakes				a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.	OK			a. Lock or Side Ring
NA			j. Hydraulic Brakes				b. Protection against shifting cargo	OK			b. Wheels and Rims
NA			k. Vacuum Systems	OK				OK			c. Fasteners
								OK			d. Welds
N/A			2. COUPLING DEVICES				7. STEERING MECHANISM	N/A			12. WINDSHIELD GLAZING
N/A			a. Fifth Wheels				a. Steering Wheel Free Play				Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions)
N/A			b. Pintle Hooks				b. Steering Column				
NA			c. Drawbar/Towbar Eye	N/A			c. Front Axle Beam and All Steering Components Other Than Steering Column				13. WINDSHIELD WIPERS
NA			d. Drawbar/Towbar Tongue	N/A			d. Steering Gear Box				Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
OK			e. Safety Devices	N/A			e. Pitman Arm				
OK			f. Saddle-Mounts	N/A			f. Power Steering				List any other condition which may prevent safe operation of this vehicle.
							g. Ball and Socket Joints				
N/A			3. EXHAUST SYSTEM				h. Tie Rods and Drag Links				
			a. Any exhaust system determined to be leaking at a point forward of or directly below the driver/sleeper compartment.	N/A			i. Nuts				
NA			b. A bus exhaust system leaking or discharging to the atmosphere in violation of standards (1), (2) or (3).	N/A			j. Steering System				
			c. No part of the exhaust system of any motor vehicle shall be so located as would be likely to result in burning, charring, or damaging the electrical wiring, the fuel supply, or any combustible part of the motor vehicle.	N/A							
				OK			8. SUSPENSION				
							a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.	NA			
				OK			b. Spring Assembly				
							c. Torque, Radius or Tracking Components.				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION REPORT IN ACCORDANCE WITH 49 CFR 396.